



CENTREplus: for simple centering of boreholes and spindles

Application:

To determine centres of a circle to the spindle with a probing accuracy < 0.010 mm. The dial gauge shows 1/100 mm sub-steps.

Design:

Thanks to the horizontal arrangement of the dial gauge, you can always see the dial gauge.




Fine adjustment:

With the fine adjustment, you can position the dial gauge precisely.



Clamping:

With the two knurled screws, you can clamp the dial gauge quickly and precisely.



Optional spare part:

You can order separately a short-arm which increases the measuring range up to Ø200 mm.

Article-No.	Description	Shank
0017C1012	Coaxial indicator CENTREplus Ø0-Ø110	Ø12
0017C1098	Spare dial gauge	
0017C1099	Short-arm (measuring range up to Ø200)	

